



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 100 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | B   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 4   | <b>Setup No:</b> | 3        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2215                |                       | Ken Oak             | ROAD                |

|                     |              |                       |             |                  |
|---------------------|--------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 9=Yard-Side | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 50          |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 7

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0007.JPG

**Image Status:** Image found and displayed.



**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0008.JPG

**Image Status:** Image found and displayed.

**Photo No:**


**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 100 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | B   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 5   | <b>Setup No:</b> | 3        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2215                |                       | Ken Oak             | ROAD                |

|                     |           |                       |             |                  |
|---------------------|-----------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 18= Other | <b>Location:</b>      | 8=Yard-Back | <b>Severity:</b> |
| <b>Sector:</b>      | 1=Public  | <b>Drainage Area:</b> | 150         |                  |

**Comments:** Unkown source

## SMOKE TEST PHOTOS



**Photo No:** 9

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0009.JPG

**Image Status:** Image found and displayed.



**Photo No:** 10

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0010.JPG

**Image Status:** Image found and displayed.

**Photo No:**


**Filename Path:**

**Image Status:** No image name specified.

## SMOKE TESTING OBSERVATION SUMMARY

# Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

**Image Status:** Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 100 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | B   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 6   | <b>Setup No:</b> | 3        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2215                |                       | Ken Oak             | ROAD                |

|                     |           |                       |              |                  |
|---------------------|-----------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 18= Other | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private | <b>Drainage Area:</b> | 100          |                  |

**Comments:** Unkown source

## SMOKE TEST PHOTOS



**Photo No:** 11

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0011.JPG

**Image Status:** Image found and displayed.



**Photo No:** 14

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0014.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 100 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | B   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | Y       |
| <b>Defect No:</b>     | 7   | <b>Setup No:</b> | 3        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2215                |                       | Ken Oak             | ROAD                |

|                     |                 |                       |        |                  |
|---------------------|-----------------|-----------------------|--------|------------------|
| <b>Source Type:</b> | 14= Catch Basin | <b>Location:</b>      | 6=Curb | <b>Severity:</b> |
| <b>Sector:</b>      | 1=Public        | <b>Drainage Area:</b> | 2200   |                  |

**Comments:** corner of streets

## SMOKE TEST PHOTOS



**Photo No:** 12

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0012.JPG

**Image Status:** Image found and displayed.



**Photo No:** 13

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0013.JPG

**Image Status:** Image found and displayed.



**Photo No:** 14

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0014.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 100

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\100.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 1   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2214                |                       | W Rogers            | AVE                 |

|                     |                  |                       |          |                  |
|---------------------|------------------|-----------------------|----------|------------------|
| <b>Source Type:</b> | 02= Service Line | <b>Location:</b>      | 12=Alley | <b>Severity:</b> |
| <b>Sector:</b>      | 1=Public         | <b>Drainage Area:</b> | 20       |                  |

**Comments:** hole in ground

## SMOKE TEST PHOTOS



**Photo No:** 29

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0029.JPG

**Image Status:** Image found and displayed.



**Photo No:** 30

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0030.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 2   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2212                |                       | W Rogers            | AVE                 |

|                     |                  |                       |             |                  |
|---------------------|------------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 02= Service Line | <b>Location:</b>      | 8=Yard-Back | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private        | <b>Drainage Area:</b> | 300         |                  |

**Comments:** hole in ground

## SMOKE TEST PHOTOS



**Photo No:** 31

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0031.JPG

**Image Status:** Image found and displayed.



**Photo No:** 32

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0032.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 3   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2210                |                       | W Rogers            | AVE                 |

|                     |                  |                       |             |                  |
|---------------------|------------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 02= Service Line | <b>Location:</b>      | 8=Yard-Back | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private        | <b>Drainage Area:</b> | 75          |                  |

**Comments:** hole in ground

## SMOKE TEST PHOTOS



**Photo No:** 33

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0033.JPG

**Image Status:** Image found and displayed.



**Photo No:** 35

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0035.JPG

**Image Status:** Image found and displayed.



**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID101-A3\2005\_0523Image008.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 4   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2210                |                       | W Rogers            | AVE                 |

|                     |                  |                       |             |                  |
|---------------------|------------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 02= Service Line | <b>Location:</b>      | 8=Yard-Back | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private        | <b>Drainage Area:</b> | 100         |                  |

**Comments:** hole in ground

## SMOKE TEST PHOTOS



**Photo No:** 34

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0034.JPG

**Image Status:** Image found and displayed.



**Photo No:** 35

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0035.JPG

**Image Status:** Image found and displayed.



**Photo No:** 8

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID101-A3\2005\_0523Image008.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 5   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2206                |                       | W Rogers            | AVE                 |

|                     |                  |                       |             |                  |
|---------------------|------------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 02= Service Line | <b>Location:</b>      | 8=Yard-Back | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private        | <b>Drainage Area:</b> | 50          |                  |

**Comments:** hole in ground

## SMOKE TEST PHOTOS



**Photo No:** 36

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0036.JPG

**Image Status:** Image found and displayed.



**Photo No:** 38

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0038.JPG

**Image Status:** Image found and displayed.



**Photo No:** 12

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID101-A5\_2005\_0523Image012.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 6   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2206                |                       | W Rogers            | AVE                 |

|                     |                  |                       |             |                  |
|---------------------|------------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 02= Service Line | <b>Location:</b>      | 8=Yard-Back | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private        | <b>Drainage Area:</b> | 50          |                  |

**Comments:** hole in ground

## SMOKE TEST PHOTOS



**Photo No:** 37

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0037.JPG

**Image Status:** Image found and displayed.



**Photo No:** 38

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0038.JPG

**Image Status:** Image found and displayed.



**Photo No:** 12

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID101-A5\_2005\_0523Image012.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 7   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2214                |                       | W Rogers            | AVE                 |

|                     |                  |                       |          |                  |
|---------------------|------------------|-----------------------|----------|------------------|
| <b>Source Type:</b> | 02= Service Line | <b>Location:</b>      | 12=Alley | <b>Severity:</b> |
| <b>Sector:</b>      | 1=Public         | <b>Drainage Area:</b> | 25       |                  |

**Comments:** hole in ground

## SMOKE TEST PHOTOS



**Photo No:** 39

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0039.JPG

**Image Status:** Image found and displayed.



**Photo No:** 30

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0030.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 8   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2214                |                       | W Rogers            | AVE                 |

|                     |                  |                       |             |                  |
|---------------------|------------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 02= Service Line | <b>Location:</b>      | 9=Yard-Side | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private        | <b>Drainage Area:</b> | 50          |                  |

**Comments:** hole in ground

## SMOKE TEST PHOTOS



**Photo No:** 40

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0040.JPG

**Image Status:** Image found and displayed.



**Photo No:** 30

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0030.JPG

**Image Status:** Image found and displayed.



**Photo No:** 11

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\UTID101-A8\2005\_0523Image011.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | B   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 1   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2303                |                       | Ken Oak             | ROAD                |

|                     |              |                       |             |                  |
|---------------------|--------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 8=Yard-Back | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 0           |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 15

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0015.JPG

**Image Status:** Image found and displayed.



**Photo No:** 16

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0016.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | B   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 2   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2311                |                       | Ken Oak             | ROAD                |

|                     |                  |                       |            |                  |
|---------------------|------------------|-----------------------|------------|------------------|
| <b>Source Type:</b> | 02= Service Line | <b>Location:</b>      | 4=Driveway | <b>Severity:</b> |
| <b>Sector:</b>      | 1=Public         | <b>Drainage Area:</b> | 1000       |                  |

**Comments:** behind 2307 Ken Oak Road

## SMOKE TEST PHOTOS



**Photo No:** 17

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0017.JPG

**Image Status:** Image found and displayed.



**Photo No:** 18

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0018.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 101 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | B   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 3   | <b>Setup No:</b> | 4        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2315                |                       | Ken Oak             | ROAD                |

|                     |                  |                       |             |                  |
|---------------------|------------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 02= Service Line | <b>Location:</b>      | 8=Yard-Back | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private        | <b>Drainage Area:</b> | 100         |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 19

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0019.JPG

**Image Status:** Image found and displayed.



**Photo No:** 20

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0020.JPG

**Image Status:** Image found and displayed.



**Photo No:** 14

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\Retakes\[UTID101-B3]\_2005\_0523Image014.JPG


**Image Status:** Image found and displayed.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 101

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\101.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 102 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 1   | <b>Setup No:</b> | 5        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2311                |                       | South               | ROAD                |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 0            |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 41

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0041.JPG

**Image Status:** Image found and displayed.



**Photo No:** 42

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0042.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 102

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\102.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 102 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 2   | <b>Setup No:</b> | 5        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2402                |                       | Ken Oak             | ROAD                |

|                     |              |                       |             |                  |
|---------------------|--------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 8=Yard-Back | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 0           |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 43

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0043.JPG

**Image Status:** Image found and displayed.



**Photo No:** 45

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0045.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 102

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\102.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 102 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | A   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 3   | <b>Setup No:</b> | 5        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2402                |                       | Ken Oak             | ROAD                |

|                     |              |                       |             |                  |
|---------------------|--------------|-----------------------|-------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 8=Yard-Back | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 200         |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 44

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0044.JPG

**Image Status:** Image found and displayed.



**Photo No:** 45

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_A\A\_2004\_0907Image0045.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 102

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\102.tif

Image Status: Image found and displayed.

*NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.*





# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 102 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | B   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 1   | <b>Setup No:</b> | 5        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2314                |                       | South               | ROAD                |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 0            |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 21

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0021.JPG

**Image Status:** Image found and displayed.



**Photo No:** 22

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0022.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 102

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\102.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

|                       |     |                  |          |                              |         |
|-----------------------|-----|------------------|----------|------------------------------|---------|
| <b>Unique Test ID</b> | 102 | <b>Date:</b>     | 9/7/2004 | <b>MeterBasin:</b>           | 01_WR11 |
| <b>Observer ID:</b>   | B   | <b>Crew:</b>     | T-1      | <b>Dye Test Recommended:</b> | N       |
| <b>Defect No:</b>     | 2   | <b>Setup No:</b> | 5        | <b>Priority CCTV:</b>        |         |

|                     |                       |                     |                     |
|---------------------|-----------------------|---------------------|---------------------|
| <b>House Number</b> | <b>Street Prefix:</b> | <b>Street Name:</b> | <b>Street Type:</b> |
| 2310                |                       | South               | ROAD                |

|                     |              |                       |              |                  |
|---------------------|--------------|-----------------------|--------------|------------------|
| <b>Source Type:</b> | 04= Cleanout | <b>Location:</b>      | 7=Yard-Front | <b>Severity:</b> |
| <b>Sector:</b>      | 2=Private    | <b>Drainage Area:</b> | 40           |                  |

**Comments:**

## SMOKE TEST PHOTOS



**Photo No:** 23

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0023.JPG

**Image Status:** Image found and displayed.



**Photo No:** 24

**Filename Path:**

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke  
Testing\Pictures\0907-2004\T-1\PLAYER\_B\B\_2004\_0907Image0024.JPG

**Image Status:** Image found and displayed.

**Photo No:**

**Filename Path:**


**Image Status:** No image name specified.



# SMOKE TESTING OBSERVATION SUMMARY

Western Run Pilot Project - Baltimore Maryland

## FIELD SKETCH



Sketch No: 102

### Filename Path:

X:\Baltimore City\Western Run Pilot Area - Data Files\Smoke Testing\Pictures\Sketches\102.tif

Image Status: Image found and displayed.

NOTE: Sanitary sewer alignments and connectivity in the Western Run GIS have been revised following smoke testing to reflect updated information from various sources and may no longer match the field sketches shown.